

Fig. 1





Fig. 2



PORTINE SUPPLY

STATE OF THE S

Fig. 3B

PCT/GB2004/050035 3/12




FIG. 3C




FIG. 4




FIG. 5




FIG. 6




FIG. 7






FIG. 8





[P = primary winding - \$ = secondary winding]

PPPPPP PPPPP SSSSS SSSSS PPPPPP SSSSS PPPPPP SSSSSS

Stacked-1

Stacked-2

FIG. 11





FIG. 12







FIG. 14






FIG. 16




FIG. 17




FIG. 18




FIG. 19